

BMW 2016 435xi Gran Coupé Coding

:Green: Works; Blue: Not working

1. Disable initial 3 chime seatbelt warning (Green: Works)

ACSM 3000 Initialwarnung_GWF_IW nicht_aktiv / Werte=00

2. If Auto-Lock is enabled, then all doors will unlock at ignition shutoff.

FEM_BODY 3040 CLM_UNLOCK_KL15OFF_AFTER_PIA_AUTO_LOCK aktiv

3. Change the Comfort Access trunk opening delay. (HEX value by 0.1 secs)

FEM_BODY 3040 CLM_TIMEOUT_HK_SMO (wert_02) werte = 03

4. Close Windows/Fold Mirrors when holding lock on Key Fob.

FEM_BODY 3053 KOMFORTSCHLIESSUNG_FB aktiv

5. Change the triple blinker blinks to any amount. (Value is XX + 1).

FEM_BODY 3060 BLINKZYKLEN_ANZAHL_TIPP werte = X-1 = 6

6. Activate Rear Fog Lamp Switch - Part 1

FEM_BODY 3060 NSL_VERBAUT Verbaut

7. Ambiance lighting controlled independent from Dimmer Switch

FEM_BODY 3070 AMBIENTE_NACHFUEHRUNG nicht_aktiv

8. Door handle LEDs light up when engaged in Reverse

FEM_BODY 3070 OVT_BEI_RUECKFAHRLICHT aktiv

9. Activate Variable Light Distribution

FEM_BODY 3073 LUT_FLC_FORWARDLIGHTING_Y werte = 9C,9C,9C
(F20_mit_AFS)

FEM_BODY 3073 C_AFS_ENA werte = 01 (ENABLE)

10. Fold Mirrors when holding lock on Key Fob or Comfort Access.

FEM_BODY 3110 ASP_BEIKLAPPEN_BEI_KOMFORTSCHLIESSEN aktiv

BMW 2016 435xi Gran Coupé Coding - 2

11. Unfold Mirrors on vehicle unlock via Key Fob or Comfort Access.

FEM_BODY 3110 ASP_AUSKLAPPEN_NACH_KOMFORTSCHLIESSEN aktiv

12. Changes the speed at which the side mirrors will auto-unfold. (Value in HEX)

FEM_BODY 3110 ASP_GESCHWINDIGKEIT_AUTO_AUSKLAPPEN 14 (20km/h)

13. Set time steering wheel heater will remain on after activation.

FEM_BODY 3140 NACHLAUFZEIT_LENKRADHEIZUNG 24 hours

14. Button on driver-side will be enabled to CLOSE the trunk.

HKFM 3010 SCH_TOEHKI aktiv

15. Button on key fob will be enabled to CLOSE the trunk.

HKFM 3010 SCH_FBD aktiv

16. Required for SCH_FBD and SCH_TOEHKI to work.

HKFM 3010 TASTER_FBD aktiv

17. Removes speed requirement to watch videos.

HU_NBT2_EVO 3000 HMI, 96

VIDEO_SPEEDLOCK_CONDITION none

VIDEO_HANDBRAKE nicht_aktiv

VIDEO_FRONT_LOCKED nicht_aktiv_

SPEEDLOCK_X_KMH_MIN Unknown Werte= FF

SPEEDLOCK_X_KMH_MAX Unknown Werte= FF

18. Removes iDrive Initial Disclaimer.

HU_NBT2_EVO 3001 EXBOX, 96 LEGAL_DISCLAIMER_TIME kein_Id

BMW 2016 435xi Gran Coupé Coding - 3

19. Removes disclaimer for all cameras and PDC

HU_NBT2_EVO 3001 EXBOX, 96 MACRO_CAM_LEGALDISCLAIMER kein_Id

20. Set volume level to be retained at 40% rather than startup on 25%.

HU_NBT2_EVO 3002 AUDIO_TUNER_TRAFFIC, 96 VOL_MAX_ON werte=28

21. Enable Video Playback via USB (.avi, .mp4, .mkv, .m4v, etc.)

HU_NBT2 3003 TELEPHON_TELEMATIK_ONLINE, 95 API_USB_VIDEO both

22. Adds Developer Menu to Settings. (Shows Build/Date/Versions/etc)

HU_NBT2_EVO 3006 NAVIGATION, 64 ENTWICKLER_MENUE aktiv

23. Disable house number first on destination input screen.

HU_NBT2_EVO 3006 NAVI 3006 NAVI_DESTINATION_INPUT_US nicht_aktiv

24. Enables importing a trip into Navigation via USB Drive

HU_NBT2_EVO 3006 NAVIGATION, 64 NAVI_TRIP_IMPORT aktiv

25. Enable navi augmented reality guidance: MMI shows additional check box.

HU_NBT2_EVO 3006 NAVI NAVI_AUGMENTED_REALITY aktiv

26. Changes Navigation Voice from English to British English - Part 1

HU_NBT2_EVO 3007 LANGUAGE, 32 LANGUAGE_ENGLISH_UK master

27. Changes Navigation Voice from English to British English - Part 2

HU_NBT_EVO 3007 LANGUAGE, 32 LANGUAGE_ENGLISH_US nicht_aktiv

28. Adds the vehicle's current speed to the BC cycle list (Displays on KOMBI screen)

KOMBI 3000 BC_DIGITAL_V aktiv

BMW 2016 435xi Gran Coupé Coding - 4

29. Activate Rear-Left Fog Lamp - Part 2

REM 3063 Mapping_Nebelschlussl_L_output nsl_l

30. Activate Rear-Right Fog Lamp - Part 3

REM 3063 Mapping_Nebelschlussl_R_output nsl_r

31. Activates 'Easy Entry' (Will stop moving forward if gear is engaged)

SM2 3000 EINAUSSTIEGSHILFE Modus_FA_SLV